



Speed Chart for Pneumatic Actuators

MODEL	DOUBLE ACTING	SPRING RETURN	
	OPEN/CLOSE	OPEN	CLOSE
30	<1	1	1.5
40	<1	1	1.5
50	<1	1	1.5
60	<1	1	1.5
70	<1	1	1.5
80	<1	1	1.5
90	<1	1	2
100	1	1	2
120	1.5	1.5	3
140	2	2	3
160	3.6	3.5	5
190	4.5	4.5	6
200	5	5.5	10
240	5	5.5	12
270	5	5.5	16
300	6	6	22
350	6	6	38
400	10	9	50